






SPJ-51429



## TEMP.&amp; WATER PRESSURE REQUIREMENTS





Working Pressure: 1~3 bar





Required Temperature: 5-65°C

Note: Above values are the recommended values for Getting Conventional Outputs.

## TECHNICAL DRAWING












Apply soft cotton cloth



Apply soft cotton cloth




**✗ DON'T**



**✗ DON'T**

Don't apply Scrub



Steps & Cleaning agents requirements for Aerator Cleaning.

